



Douglas A. Ducey
Governor

ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY



Henry R. Darwin
Director

Water Quality Complaint Inspection Report

Facility Name: Collection System – Section 11 WWTP	Complaint No: 15040: Follow up to SSO	
Physical Location: NW of address 6180 E. Valley View Dr.; manhole near golf cart track City, State, Zip: Florence, AZ	Inspection No.: 303603	
County: Pinal	Arrival Date and Time: 6/6/2018 4:00 PM	
Mailing Address: 968 E. Hunt Hwy City, State, Zip: San Tan Valley, AZ 85143	Inspector(s): Joshua Litt	
Coordinates (for new locations): Latitude: 33°5'26.0844"N Longitude: 111°30'1.584"W	Inspector Phone: 602-771-4805 Inspector Email: jl16@azdeq.gov	
Owner/Responsible Party: Johnson Utilities, L.L.C.	Was Inspection Announced? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Onsite Contact Person(s)/Facility Operator(s): Matthew Hipsher Assistant Manager – Collection System	Weather: Sunny and hot	
Nearest Receiving Water, if applicable (indicate distance): There are no perennial or ephemeral surface water bodies		
Inspection Report Issued: Choose an item.	Facility Initial:	ADEQ Initial:
Results of Inspection: <input checked="" type="checkbox"/> No deficiencies were noted during the course of the inspection. No ADEQ action will result from this inspection. <input type="checkbox"/> Potential deficiencies were noted during the course of the inspection. Additional correspondence regarding this inspection may be forthcoming.		
Comments: See below.		
Attachments: Attachment A – Photograph Log		
PHOTOGRAPHS TAKEN DURING INSPECTIONS ARE AVAILABLE ON REQUEST		

Description of the Complaint	<p>On June 5, 2018, at 7:30 PM, a manhole was observed to be overflowing with sewage. The photo that was provided showed the Hunt Hwy in the distance and power lines above.</p> <p>Another complaint said there were overflowing manholes on Valley View Drive next to a golf cart track.</p>
Observations:	<p>I arrived at Mirage at Magic Ranch and traveled down to the South/Southeast on E. Valley View Drive (<i>See Attachment A – Photo #1</i>), until I saw a manhole that had staining around it. It was located in an area next to a golf cart track and had powerlines overhead. My arrival time was 4:00 PM. As I walked to the manhole, I noticed there was a retention pond with some grass discoloration. There was a small drainage outlet to the retention pond from the manhole area. When I walked to the retention pond, I noticed at the end of the drain, there was wet mud, wet grass, and some discoloration (<i>See Attachment A – Photo # 3</i>). I also observed disinfectant (granular chlorine) powder on the grass, mud and rocks (<i>See Attachment A – Photo # 4</i>).</p> <p>At the manhole, I observed more granular chlorine powder (<i>See Attachment A – Photo # 5</i>). There also was a brownish-tannish stain on the street (<i>See Attachment A – Photo # 6 and # 7</i>). I followed this staining south along E. Valley View Dr. from the empty desert landscape lot to 6208 E. Valley View Dr. (<i>See Attachment A – Photo # 2</i>). There was no further staining south of this location. It appears that the SSO was cleaned up.</p>
Comments and Potential Deficiencies:	<p>Johnson Utilities sent the ADEQ a 24-Hr Notification of this SSO. Corrective actions were made.</p>

