

**Public Record – Summary Information on Underground Storage Tanks (USTs)
Arizona Department of Environmental Quality (ADEQ)**

Report Period: October 1, 2015 – September 30, 2016

General Information:

Total Number of UST Facilities: 2,308
Total Number of Open USTs: 6,416

Summary Information for On-Site UST Inspections:

Number of UST Facilities Inspected: 823
Percent Significant Compliance¹: 86%

Summary Information for Leaking UST (LUST) Releases²:

Number of Confirmed LUST Releases: 87 (at 57 facilities)

Summary Information for Release Sources and Causes:

| Source | | | Cause | | | | | | | | | | | | | |
|--------------------------|----|-----|-------|------|----------|------|------------------|------|-----------|------|------------------|------|-------|------|---------|------|
| | # | % | Spill | | Overfill | | Phys/Mech Damage | | Corrosion | | Install Problems | | Other | | Unknown | |
| | | | # | % | # | % | # | % | # | % | # | % | # | % | | |
| Tank | 31 | 36 | | | | | | | 3 | 10 | | | | | 28 | 90 |
| Piping | 22 | 25 | | | | | 1 | 5 | | | | | | | 21 | 95 |
| Dispenser | 33 | 38 | | | | | 1 | 2 | | | | | | | 32 | 98 |
| Submersible Turbine Pump | 1 | 1 | | | | | | | | | | | | | 1 | 100 |
| Delivery Problem | | | | | | | | | | | | | | | | |
| Other | | | | | | | | | | | | | | | | |
| Totals | 87 | 100 | | xxxx | | xxxx | 2 | xxxx | 3 | xxxx | | xxxx | | xxxx | 82 | xxxx |

¹ Percent compliance measures significant compliance with Arizona's UST regulatory requirements based on an on-site compliance inspection. Significant or major violations, such as non-compliance with the presence or operational capability of release detection, corrosion protection, overfill or spill prevention equipment would result in issuance of a Notice of Violation.

² Release, source and cause information is based on data associated with the 87 LUST releases reported during this reporting period. All open LUST release case files, 661 to date, are tracked in the Azurite database and are managed by ADEQ case managers within the LUST Section.

To obtain more information on UST inspection and compliance issues, please call (602) 771-4196. To obtain more information on LUST issues, please call (602) 771-4341.