

Acknowledgement of Samples Received

Addr: **Arizona Department of Environmental Quality**
1110 West Washington Street
Phoenix, AZ 85007

Attn: David Burchard
Phone: (602) 771-4298

Client ID: ADEQ-LEAD
Folder #: 661841
Project: GANADO-USD
Sample Group: Ganado Intermediate School

Project Manager: Thomas.D.French
Phone: (480) 778-1558
PO #: ADEQ16-116686:3
Sampler: Keith Long

The following samples were received from you on **May 23, 2017** at **1025**. They have been scheduled for the tests listed below each sample. If this information is incorrect, please contact your service representative. Thank you for using Eurofins Eaton Analytical.

Sample #	Sample ID	Sample Date
<u>201705230595</u>	1001	05/18/2017 0535
Sample Type: Classroom Sink Facility ID: Building 100 Part 1 Sample Point ID: D-1 Classroom #13		
<div>@ICPMS</div> <div>Freight - Outbound</div> <div>Freight - Return</div>		
<u>201705230596</u>	1001	05/18/2017 0613
Sample Type: Classroom Facility ID: Building 100 Part 1 Sample Point ID: D-1 Classroom #13		
<div>@ICPMS</div>		
<u>201705230597</u>	1002	05/18/2017 0542
Sample Type: Classroom Sink Facility ID: Building 100 Part 2 Sample Point ID: E1 E40-0		
<div>@ICPMS</div>		
<u>201705230598</u>	1003	05/18/2017 0552
Sample Type: Kitchen Sink Facility ID: Kitchen Addition Sample Point ID: Intermediate Discharge Sink F		
<div>@ICPMS</div>		

Test Description

@ICPMS -- ICPMS Metals