

## Acknowledgement of Samples Received

Addr: **Arizona Department of Environmental Quality**  
1110 West Washington Street  
Phoenix, AZ 85007

Attn: David Burchard  
Phone: (602) 771-4298

Client ID: ADEQ-LEAD  
Folder #: 661851  
Project: GANADO-USD  
Sample Group: Ganado Middle School

Project Manager: Thomas.D.French  
Phone: (480) 778-1558  
PO #: ADEQ16-116686:3  
Sampler: Kevin Waterman

The following samples were received from you on **May 23, 2017** at **1028**. They have been scheduled for the tests listed below each sample. If this information is incorrect, please contact your service representative. Thank you for using Eurofins Eaton Analytical.

Sample #	Sample ID	Sample Date
<u>201705230610</u>	1059	05/18/2017 0530
Sample Type: Conference Room Kistchen Sink Facility ID: 1996 Addition Sample Point ID: Kitchen @ICPMS                      Freight - Outbound                      Freight - Return		
<u>201705230611</u>	1054	05/18/2017 0535
Sample Type: Kitchen Sink Facility ID: Field House Sample Point ID: Kitchen @ICPMS		
<u>201705230612</u>	1054	05/18/2017 0534
Sample Type: Lobby Drinking Faucet Facility ID: Field House Sample Point ID: Lobby @ICPMS		
<u>201705230613</u>	1063	05/18/2017 0542
Sample Type: Classroom Sink Facility ID: Now School Sample Point ID: Classroom Sink @ICPMS		

### Test Description

@ICPMS -- ICPMS Metals