



Katie Hobbs
Governor

Arizona Department of Environmental Quality



Karen Peters
Cabinet Executive Officer
Executive Deputy Director

Report Review

Inspection ID: 445465
Permit No: 88788
Place ID: 827
AZURITE Place Name: ENERGY FUELS RESOURCES - PINYON PLAIN MINE

Inspection Type: Report Review
Type of Report: Annual Report 40 CFR Subpart B NESHAP

Date Received: 3/29/2024
Date Reviewed: 4/11/2024
Reviewer: Mariana Mendez Armendariz

Results of Inspection:

Is the report certified for truth, accuracy, and completeness by a responsible official?

- Yes – David C. Frydenlund
- No – Contact Permittee for proper signature.

Does the Permittee state they are in compliance?

- Yes – File report without contacting Permittee.
- No – Request additional information or permit deviation report as necessary.

Reviewer Comments:

In 2023, the facility reports that underground activities comprised of routine maintenance of the water rings. Mining activities resumed December 2023 and the facility commenced monitoring with EPA Method A-6 (12/3/2023). Prior to that, the monitoring was conducted using Method A-7.

The COMPLY-R modeling result was 0.0018 mrem/ year of Radon-222. This does not exceed the permit limit of 10 mrem/year.

The report includes all the necessary information as required by Condition II.A.2.b of Attachment “B” (40 CFR 61.24). No reporting deficiencies noted.

Main Office

1110 W. Washington St. | Phoenix, AZ 85007
602-771-2300

Southern Regional Office

400 W. Congress St. | Suite 433 | Tucson, AZ 85701
520-628-6733

azdeq.gov