



Katie Hobbs
Governor

Arizona Department of Environmental Quality



Karen Peters
Cabinet Executive Officer
Executive Deputy Director

Report Review

Inspection ID: 448647
Permit No: 88788
Place ID: 827
AZURITE Place Name: ENERGY FUELS RESOURCES - PINYON PLAIN MINE

Inspection Type: Report Review
Type of Report: Environmental Gamma Monitoring Results 1st Quarter 2024

Date Received: 5/2/2024
Date Reviewed: 5/22/2024
Reviewer: Mariana Mendez Armendariz

Results of Inspection:

Is the report certified for truth, accuracy, and completeness by a responsible official?

- Yes – Scott Bakken
- No – Contact Permittee for proper signature.

Does the Permittee state they are in compliance?

- Yes – File report without contacting Permittee.
- No – Request additional information or permit deviation report as necessary.

Reviewer Comments:

1st Quarter 2024 (01/03/2024 – 04/08/2024):

Badge #66: 2.62 mRem/week
 Badge #67: 2.86 mRem/week
 Badge #68: 3.17 mRem/week
 Badge #69: 2.88 mRem/week
 Badge #114: 2.06 mRem/week
 Badge #115: 2.73 mRem/week

The trigger level for this mine is 7.8 mRem/week. Since the gamma results are below the trigger level, no additional reporting is required according to Att D. Condition II.B.3.c-d.

No reporting deficiencies noted.

Main Office

1110 W. Washington St. | Phoenix, AZ 85007
602-771-2300

Southern Regional Office

400 W. Congress St. | Suite 433 | Tucson, AZ 85701
520-628-6733

azdeq.gov