



Katie Hobbs  
Governor

# ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY



Karen Peters  
Director

## Report Review

**Inspection ID:** 458966  
**Permit No:** 88788  
**Place ID:** 827  
**AZURITE Place Name:** ENERGY FUELS RESOURCES - PINYON PLAIN MINE

**Inspection Type:** Report Review  
**Type of Report:** Environmental Gamma Monitoring Results 3<sup>rd</sup> Quarter 2024

**Date Received:** 11/21/2024  
**Date Reviewed:** 12/2/2024  
**Reviewer:** Jordy Flores

### Results of Inspection:

Is the report certified for truth, accuracy, and completeness by a responsible official?

- Yes – Scott Bakken
- No – Contact Permittee for proper signature.

Does the Permittee state they are in compliance?

- Yes – File report without contacting Permittee.
- No – Request additional information or permit deviation report as necessary.

### Reviewer Comments:

3<sup>rd</sup> Quarter 2024 (07/10/2024 – 10/09/2024):

Badge #66: 3.52 mRem/week  
Badge #67: 2.70 mRem/week  
Badge #68: 2.97 mRem/week  
Badge #69: 4.43 mRem/week  
Badge #114: 2.72 mRem/week  
Badge #115: 4.01 mRem/week

The trigger level for this mine is 7.8 mRem/week. Since the gamma results are below the trigger level, no additional reporting is required according to Att D. Condition II.B.3.c-d.

No reporting deficiencies noted.

#### Main Office

1110 W. Washington Street • Phoenix, AZ 85007  
(602) 771-2300

#### Southern Regional Office

400 W. Congress Street • Suite 433 • Tucson, AZ 85701  
(520) 628-6733

[www.azdeq.gov](http://www.azdeq.gov)

printed on recycled paper