



Katie Hobbs  
Governor

# Arizona Department of Environmental Quality



Karen Peters  
Deputy Director

## Report Review

**Inspection ID:** 463810

**Permit No:** 88788

**Place ID:** 827

**AZURITE Place Name:** ENERGY FUELS RESOURCES – PINYON PLAIN MINE

**Inspection Type:** Quarterly Report Review

**Type of Report:** Environmental Gamma Monitoring Results 4<sup>th</sup> Quarter 2024

**Date Received:** 2/17/2025

**Date Reviewed:** 2/19/2025

**Reviewer:** Jordy Flores

### Results of Inspection:

Is the report certified for truth, accuracy, and completeness by a responsible official?

- Yes – Scott Bakken
- No – Contact Permittee for proper signature.

Does the Permittee state they are in compliance?

- Yes – File report without contacting Permittee.
- No – Request additional information or permit deviation report as necessary.

### Reviewer Comments:

4<sup>th</sup> Quarter 2024 (10/9/2024 – 1/9/2025):

Badge #66: 3.36 mRem/week

Badge #67: 3.04 mRem/week

Badge #68: 2.98 mRem/week

Badge #69: 5.12 mRem/week

Badge #114: 2.64 mRem/week

Badge #115: 4.47 mRem/week

The trigger level for this mine is 7.8 mRem/week. Since the gamma results are below the trigger level, no additional reporting is required according to Att D. Condition II.B.3.c-d.

No reporting deficiencies noted.

#### Main Office

1110 W. Washington Street • Phoenix, AZ 85007  
(602) 771-2300

#### Southern Regional Office

400 W. Congress Street • Suite 433 • Tucson, AZ 85701  
(520) 628-6733

[www.azdeq.gov](http://www.azdeq.gov)

printed on recycled paper